

GET-OUT**OP-Line****(4LD-CH3/4,SQ4,SL)**

BOX-N SL TR-BY PA AL	PA TR-BY PA UTB SQ4 TR-BY RLG	SQ4 TR-BY BOX-N RLG	SQ2 TR-BY R/L PA AL
----------------------------------	---	------------------------------	---------------------------------

0-LINE→(P-O,CC,SW,RC,SWP1/.(4LD-CH H:PRM1/2,Lead-R,VL,B

T 1/4 CC B-R AL RLG ON3 PRM	SW SP-TOP CC SCT-B RLG	PA 1/2 TAG SP-CC CC BOX-N RLG	P-O SP-CH-TH B-R BL ST AL
---	------------------------------------	--	--

0-LINE→(P-O,CC,SW,RC,SWP1/.(4LD-CH H:PRM1/2,Lead-R,VL,B

© ST SQ3 ON 3 ECH 3 AL	© P-O CC SW RC RLG	PA BL ST P-T-C C:PA BOXN RLG	SP-TOP C:CC B-R FE/L W-PA Leads:TR AL
---------------------------------	--------------------------------	--	---

0-LINE→(P-O,CC,SW,RC,SWP1/.(4LD-CH H:PRM1/2,Lead-R,VL,B

T 1/4 B:Diag PA E:CLV-L C:SQ2 PA , UTB SW , RLG	T 1/4 CC B-R P-T-C C:PA AL	ST PA TR-BY R/L BOXN RLG	R/L P-O SP-CH-TH G:CC X 2 EXT RLG
--	---	---	--

0-LINE→(P-O,CC,SW,RC,SWP1/.(4LD-CH H:PRM1/2,Lead-R,VL,B

ST PA TR-BY SQ3 AL	PA P:TR SL 8CH 3 AL	P-O HNG SP-CC X 2 HNG CC RLG	
--------------------------------	---------------------------------	---	--

BL)

BL)

BL)

BL)